



# VAPORMIST® EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC

DATE	REV	RECORD	DR
11/13	A	E.C.# 6157	JK
1/14	B	E.C.# 6172	JK



- NOTES:
- WATER LEVEL PROBE GROUND MUST BE CONNECTED TO TANK FOR PROPER HUMIDIFIER OPERATION.
  - REFER TO VM ELECTRICAL DATA SHEET.

**POWER WIRING**  
CONTROL CIRCUIT WIRING  
FIELD WIRING  
OPTIONAL FACTORY  
OPTIONAL FIELD

**LEGEND**

- |   |                 |   |                   |
|---|-----------------|---|-------------------|
| K | RELAY/CONTACTOR | Y | SOLENOID          |
| T | TRANSFORMER     | N | SENSOR            |
| Q | CIRCUIT BREAKER | J | JUMPER            |
| S | SWITCH          | E | WATER PROBE       |
| H | HEATER          | M | MOTOR/FAN         |
| F | FUSE            | R | SOLID STATE RELAY |

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

		VM, STANDARD WATER, SSR, SDU W/TRANSFORMER WIRING DIAGRAM	
		MAT'L:	P/N
SCALE:	DATE: 11/6/13	VM-VL5-42	
DRAWN BY: KROG			