HUMIDI–TECH® EVAPORATIVE HUMIDIFIER
FACTORY WIRING DIAGRAM W/VL

DATE	REV	RECORD	DR
5/15	A	E.C.# 6396	JK
6/17	B	E.C.# 6575	JK
7/21	C	E.C.# 7011	JK



NOTES:

1. FOR THREE PHASE SYSTEM, THE THREE PHASE LOAD IS USED AND THIS WIRE IS FACTORY INSTALLED.
2. WATER LEVEL PROBE GROUND MUST BE CONNECTED TO TANK FOR PROPER HUMIDIFIER OPERATION.
3. ONLY USED ON THREE PHASE POWER.
4. REFER TO HT ELECTRICAL DATA SHEET.

POWER WIRING
CONTROL CIRCUIT WIRING
FIELD WIRING
OPTIONAL FACTORY
OPTIONAL FIELD

LEGEND

K	RELAY/CONTACTOR	Y	SOLENOID
T	TRANSFORMER	N	SENSOR
Q	CIRCUIT BREAKER	J	JUMPER
S	SWITCH	E	WATER PROBE
H	HEATER	M	MOTOR/FAN
F	FUSE	LF	LINE FILTER

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

drSteem™	HT, STANDARD WATER W/SSR, SDU, WIRING DIAGRAM	
	MAT'L:	
	SCALE:	P/N HT–VL–18E
	DRAWN BY: JK	
	DATE: 5/15/15	