VAPORMIST® EVAPORATIVE HUMIDIFIER
FACTORY WIRING DIAGRAM WITH VAPOR–LOGIC

DATE	REV	RECORD	DR
5/15	A	E.C.# 6396	JK
4/17	B	E.C.# 6551	JK
4/21	C	E.C.# 6969	JK





NOTES:

1. FOR THREE PHASE SYSTEM, THE THREE PHASE LOAD IS USED AND THIS WIRE IS FACTORY INSTALLED.
2. WATER LEVEL PROBE GROUND MUST BE CONNECTED TO TANK FOR PROPER HUMIDIFIER OPERATION.
3. REFER TO VM ELECTRICAL DATA SHEET.

POWER WIRING
- CONTROL CIRCUIT WIRING
- FIELD WIRING
- OPTIONAL FACTORY
- OPTIONAL FIELD

LEGEND

K	RELAY/CONTACTOR	Y	SOLENOID
T	TRANSFORMER	N	SENSOR
Q	CIRCUIT BREAKER	J	JUMPER
S	SWITCH	E	WATER PROBE
H	HEATER	M	MOTOR/FAN
F	FUSE		

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

driSteem

VM, STANDARD WATER DIAGRAM

MAT'L:

SCALE:

DRAWN BY: JK

DATE: 5/15/15

P/N VM–VL–1