

HIGH PRESSURE DISPERSION (UP TO 16 ZONES)



STAGING/
DEPRESSURIZATION
VALVES
(MAX 3 EACH)

LEGEND

POWER WIRING

ETHERNET CABLE


24VAC 2-WIRE



HIGH PRESSURE PUMP

WIRING DIAGRAM
 HPAS-PS-VL-S = SINGLE PUMP, 1 PHASE POWER
 HPAS-PS-VL-S-3 = DOUBLE PUMP, 3 PHASE POWER
 HPAS-PS-VL-D = SINGLE PUMP, 1 PHASE POWER
 HPAS-PS-VL-D-3 = DOUBLE PUMP, 3 PHASE POWER

WATER PRETREATMENT



WIRING DIAGRAM
 WT-VL-1-1PH = SINGLE PHASE POWER
 WT-VL-2-3PH = THREE PHASE POWER