



# VAPORMIST® DI EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC

DATE	REV	RECORD	DR
5/15	A	E.C.# 6396	JK
4/17	B	E.C.# 6551	JK
4/21	C	E.C.# 6969	JK



NOTES:

1. FOR THREE PHASE SYSTEM, THE THREE PHASE LOAD IS USED AND THIS WIRE IS FACTORY INSTALLED.

2 ONLY USED ON THREE PHASE POWER.

3. REFER TO VM ELECTRICAL DATA SHEET.

**POWER WIRING**  
**CONTROL CIRCUIT WIRING**  
**FIELD WIRING**  
**OPTIONAL FACTORY**  
**OPTIONAL FIELD**

**LEGEND**

K	RELAY/CONTACTOR	Y	SOLENOID
T	TRANSFORMER	N	SENSOR
Q	CIRCUIT BREAKER	J	JUMPER
S	SWITCH	E	WATER PROBE
H	HEATER	M	MOTOR/FAN
F	FUSE	R	SOLID STATE RELAY

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

	VM, DI WATER, SSR WIRING DIAGRAM	
	MAT'L:	
	SCALE:	P/N
	DRAWN BY: JK	VM-VL-37
DATE: 5/18/15		