



# VAPORMIST® EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC

DATE	REV	RECORD	DR
1/13	A	E.C.# 5985	JK
3/13	B	E.C.# 6053	JK
1/14	C	E.C.# 6172	JK



NOTES:

- 1 WATER LEVEL PROBE GROUND MUST BE CONNECTED TO TANK FOR PROPER HUMIDIFIER OPERATION.
2. REFER TO VM ELECTRICAL DATA SHEET.

**POWER WIRING**  
CONTROL CIRCUIT WIRING  
FIELD WIRING  
OPTIONAL FACTORY  
OPTIONAL FIELD

**LEGEND**

K	RELAY/CONTACTOR	Y	SOLENOID
T	TRANSFORMER	N	SENSOR
Q	CIRCUIT BREAKER	J	JUMPER
S	SWITCH	E	WATER PROBE
H	HEATER	M	MOTOR/FAN
F	FUSE		

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

		VM, STANDARD WATER 120 VOLT DIAGRAM	
		MAT'L:	P/N
SCALE:	DATE: 1/11/13	VM-VL5-15	
DRAWN BY: KROG			