



# VAPORMIST® DI EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC

DATE	REV	RECORD	DR
11/13	A	E.C.# 6157	JK
1/14	B	E.C.# 6172	JK



- NOTES:
- FOR THREE PHASE SYSTEM, THE THREE PHASE LOAD IS USED AND THIS WIRE IS FACTORY INSTALLED.
  - ONLY USED ON THREE PHASE POWER.
  - REFER TO VM ELECTRICAL DATA SHEET.

**POWER WIRING**  
**CONTROL CIRCUIT WIRING**  
**FIELD WIRING**  
**OPTIONAL FACTORY**  
**OPTIONAL FIELD**

**LEGEND**

K	RELAY/CONTACTOR	Y	SOLENOID
T	TRANSFORMER	N	SENSOR
Q	CIRCUIT BREAKER	J	JUMPER
S	SWITCH	E	WATER PROBE
H	HEATER	M	MOTOR/FAN
F	FUSE	R	SOLID STATE RELAY

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

	VM, DI WATER, SSR WIRING DIAGRAM	
	MAT'L:	P/N
	SCALE:	VM-VL5-37
	DRAWN BY: KROG	DATE: 11/5/13