



# VAPORMIST® EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC

| DATE  | REV | RECORD     | DR |
|-------|-----|------------|----|
| 11/13 | A   | E.C.# 6157 | JK |
| 1/14  | B   | E.C.# 6172 | JK |



**NOTES:**

1. WATER LEVEL PROBE GROUND MUST BE CONNECTED TO TANK FOR PROPER HUMIDIFIER OPERATION.

2. REFER TO VM ELECTRICAL DATA SHEET.

**POWER WIRING**  
CONTROL CIRCUIT WIRING  
FIELD WIRING  
OPTIONAL FACTORY  
OPTIONAL FIELD

**LEGEND**

|   |                 |   |                   |
|---|-----------------|---|-------------------|
| K | RELAY/CONTACTOR | Y | SOLENOID          |
| T | TRANSFORMER     | N | SENSOR            |
| Q | CIRCUIT BREAKER | J | JUMPER            |
| S | SWITCH          | E | WATER PROBE       |
| H | HEATER          | M | MOTOR/FAN         |
| F | FUSE            | R | SOLID STATE RELAY |

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

|        |               |  |     |
|--------|---------------|--|-----|
|        |               | VM, STANDARD WATER, SSR, 3 $\phi$ , SDU W/TRANSFORMER WIRING DIAGRAM |     |
|        |               | MAT'L:   | P/N |
| SCALE: | DATE: 11/6/13 | VM-VL5-44  |     |