



VAPORMIST® EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC

DATE	REV	RECORD	DR
1/13	A	E.C.# 5985	JK
3/13	B	E.C.# 6053	JK
1/14	C	E.C.# 6172	JK



NOTES:

- FOR THREE PHASE SYSTEM, THE THREE PHASE LOAD IS USED AND THIS WIRE IS FACTORY INSTALLED.
- WATER LEVEL PROBE GROUND MUST BE CONNECTED TO TANK FOR PROPER HUMIDIFIER OPERATION.
- REFER TO VM ELECTRICAL DATA SHEET.

POWER WIRING
CONTROL CIRCUIT WIRING
FIELD WIRING
OPTIONAL FACTORY
OPTIONAL FIELD

LEGEND

- | | | | |
|---|-----------------|---|-------------|
| K | RELAY/CONTACTOR | Y | SOLENOID |
| T | TRANSFORMER | N | SENSOR |
| Q | CIRCUIT BREAKER | J | JUMPER |
| S | SWITCH | E | WATER PROBE |
| H | HEATER | M | MOTOR/FAN |
| F | FUSE | | |

BREAK TO EXTERNAL CONNECTIONS DIAGRAM

		VM, STANDARD WATER, SDU WIRING DIAGRAM 208V/1 & 3Ø, 240/1Ø	
		MAT'L:	P/N
SCALE:	DATE:	VM-VL5-9	
DRAWN BY: KROG			
DATE: 1/11/13			