



# VAPORMIST® DI EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC

| DATE | REV | RECORD     | DR |
|------|-----|------------|----|
| 1/13 | A   | E.C.# 5985 | JK |
| 3/13 | B   | E.C.# 6053 | JK |
| 1/14 | C   | E.C.# 6172 | JK |




**NOTES:**

- FOR THREE PHASE SYSTEM, THE THREE PHASE LOAD IS USED AND THIS WIRE IS FACTORY INSTALLED.
- REFER TO VM ELECTRICAL DATA SHEET.

**POWER WIRING**  
CONTROL CIRCUIT WIRING  
FIELD WIRING  
OPTIONAL FACTORY  
OPTIONAL FIELD

**LEGEND**

- |   |                 |   |             |
|---|-----------------|---|-------------|
| K | RELAY/CONTACTOR | Y | SOLENOID    |
| T | TRANSFORMER     | N | SENSOR      |
| Q | CIRCUIT BREAKER | J | JUMPER      |
| S | SWITCH          | E | WATER PROBE |
| H | HEATER          | M | MOTOR/FAN   |
| F | FUSE            |   |             |



BREAK TO EXTERNAL CONNECTIONS DIAGRAM

|                |               |   |     |
|----------------|---------------|---|-----|
|                |               | <b>VM, DI WATER,<br/>SDU WIRING DIAGRAM<br/>208V/1 &amp; 3Ø, 240/1Ø</b> |     |
|                |               | MAT'L:  | P/N |
| SCALE:         | DATE: 1/11/13 | <b>VM-VL5-10</b>  |     |
| DRAWN BY: KROG |               |   |     |