


VAPORMIST® DI EVAPORATIVE HUMIDIFIER FACTORY WIRING DIAGRAM WITH VAPOR-LOGIC


DATE	REV	RECORD	DR
1/13	A	E.C.# 5985	JK
3/13	B	E.C.# 6053	JK
1/14	C	E.C.# 6172	JK




NOTES:
 1. FOR THREE PHASE SYSTEM, THE THREE PHASE LOAD IS USED AND THIS WIRE IS FACTORY INSTALLED.
 2. REFER TO VM ELECTRICAL DATA SHEET.

POWER WIRING
 CONTROL CIRCUIT WIRING
 FIELD WIRING
 OPTIONAL FACTORY
 OPTIONAL FIELD

LEGEND
 K RELAY/CONTACTOR
 T TRANSFORMER
 Q CIRCUIT BREAKER
 S SWITCH
 H HEATER
 F FUSE
 Y SOLENOID
 N SENSOR
 J JUMPER
 E WATER PROBE
 M MOTOR/FAN



BREAK TO EXTERNAL CONNECTIONS DIAGRAM



		VM, DI WATER, SDU W/TRANSFORMER DIAGRAM EXCEPT 120V, 208V, 240/1Ø	
		MAT'L:	P/N
SCALE:	DATE:	VM-VL5-8	
DRAWN BY: KROG		DATE: 1/11/13	